

Bell Helicopter **TEXTRON**

A Subsidiary of Textron Inc.

TEMPORARY
REVISION
47-83-1

MODEL 47 MAINTENANCE AND OVERHAUL INSTRUCTIONS

Sheet 1 of 1
4 November 1983

MANUALS AFFECTED

47G-2A/-2A-1	47G-4/-4A
47G-3	47G-5
47G-3B/-3B-1	47G-5A
47G-3B2	47J-2/-2A
47G-3B-2A	

REFERENCE: Alert Service Bulletin 47-83-9

REASON: Add Daily Inspection for hydraulic servo cylinders.

HYDRAULIC FLIGHT CONTROL

Inspect hydraulic servo cylinder for corrosion and verify freedom of input lever pivot bolts by rotating each by hand. If stiffness or binding is felt, spray bolts with WD-40 or equivalent. If condition persists, remove cylinder from service and return to overhaul facility for repair, upgrade, and/or overhaul.

- NOTE:
1. Record this Temporary Revision on the "RECORD OF TEMPORARY REVISIONS" page.
 2. Insert this Temporary Revision facing the last item of the Daily Inspection of Section I.

